

SPECIFICATION

Taurine Reference Material

Traceable Reference Material

REQUIREMENT	SPECIFICATION
Appearance Solubility in water Loss on drying at 105°C Assay	White ~ nearly white, crystals ~ crystalline powder to pass test max.0.2% min.98.0%