## SPECIFICATION

## 47% Sulfuric Acid

REQUIREMENT	SPECIFICATION
Appearance	Colorless clear liquid
Substances reducing permanganate	to pass test
Assay	46.0~48.0%