

Code No.20-1957

SPECIFICATION

Taurine Reference Material

Traceable Reference Material

REQUIREMENT	SPECIFICATION	
Appearance	White ~ nearly white, crystals ~ crystalline powder to pass test	
Solubility in water		
Loss on drying at 105°C		max.0.2%
Assay		min.98.0%