

# SPECIFICATION

## Sulfuric Acid

for Analysis of Poisonous Metals

REQUIREMENT	SPECIFICATION
Appearance	Colorless clear liquid
Zinc (Zn)	max.5ppb
Cadmium (Cd)	max.1ppb
Mercury (Hg)	max.0.1ppb
Tin (Sn)	max.10ppb
Lead (Pb)	max.2ppb
Arsenic (As)	max.5ppb
Antimony (Sb)	max.10ppb
Vanadium (V)	max.10ppb
Selenium (Se)	max.50ppb
Chromium (Cr)	max.10ppb
Manganese (Mn)	max.10ppb
Assay	96.0~98.0%