

Code No.21-0001

# SPECIFICATION

## Ultramarine Blue

REQUIREMENT	SPECIFICATION
Appearance Loss on drying at 105°C Loss on ignition	Blue powder max.2.0% under investigation